



January, 2026

Follow Up Instructions for New Armatures/Field Coils

We recently announced changes in the motor Armatures/Field Coils, in a Service Bulletin sent out on 12/5/2025. This change was to improve the quality and performance of the motor. However, we want to emphasize the proper compatibility issue of: "NEVER MIX THE FORMER ARMATURES OR FIELD COILS WITH THE NEW ONES".

You can still use up your inventory of former Armatures/Field Coils, but can only use them on models made prior to July 2025. When you run out of the former Armatures/Field Coils, you MUST use a Motor Kit (p/n 880326A) for models made prior to July ,2025. This will provide you with the proper mix of 1 new Armature, 1 new Field Coil, and 2 Motor Brushes. Any model made after July 2025 must use the new Armature and/or Field Coil.

If there is any confusion on this topic, please give us a call at: 800-535-8674.
Thank you for your consideration.

Regards,

Jim O'Leary
Customer Support

Lou Verardi
Channel Development Manager

